

JOHNS Dave

To: Ddarold@aol.com
Subject: RE: COMPLAINT INVESTIGATION---610-9AD-10800

Dew,
Need sketch of system.

From: Ddarold@aol.com[SMTP:Ddarold@aol.com]
Sent: Friday, March 12, 1999 8:42 PM
To: johns.dave@deq.state.or.us
Cc: darold.dewey@deq.state.or.us
Subject: COMPLAINT INVESTIGATION---610-9AD-10800

Dave,

I followed up on a complaint investigation on 334 S. Marion. On 2-4-99, @ 3:35 p.m. I knocked on the door of the residence and nobody answered. The outside light was on. A car was present in the driveway. I noticed an area off to the southwest of the home where freshly dug soil was present. I did not observe any evidence of a failing system. A sketch of the site forthcoming. Dave please remind me on Monday.

State of Oregon
Department of Environmental Quality
811 S.W. 6th Avenue
Portland, Oregon 97204

Number: _____

POLLUTION COMPLAINT

Date: 2-2-99

Pollution Type:

AQ _____ SW _____ WQ XX OL _____
OB _____ HW _____ SS _____ UT _____

Time: _____

Date and Time Observed: _____

Source: RESIDENCE IN GEARHART 610-9AD-10800 0.23 ACRES

YEAR BUILT 1908
OWNER: UNION CHEMICAL CO. c/o ALBERT EVANS

Location: 334 S. MARION PO BOX 320
SEASIDE, OR 97138

GEARHART, OR CLATSOP 97138
City County Zip Phone

Description: SYSTEM INSTALLED WITHOUT PERMIT

Reported by: Name: _____

| | |
|---------------|---|
| Conf. | Address: _____ |
| Yes <u>XX</u> | City: _____ Zip: _____ |
| No _____ | County: _____ Home Phone: _____ Work Phone: _____ |

Complaint taken by: DEWEY DAROLD Referred to: DEWEY DAROLD

Action taken: _____

Referred to (Agency or Person) _____ Date: _____

Site Visit Yes _____ No. _____ Source Info Updated Yes _____ No. _____

Complainant Contacted Yes _____ Date _____

Date Resolved _____ Time Spent _____

Correspondence Attached Yes _____ No _____ To Follow _____

File Under _____

See Map 6 10 9AC

KRUSES FIRST ADD

AVE.

AVE.

AVE.

APR 1 1996

NORTH COAST BRANCH OFFICE
WARRENTON

| | | | |
|----|-------|-------|----|
| 11 | 10100 | 10200 | 30 |
| 12 | 10300 | 11300 | 29 |
| 13 | | 11200 | 28 |
| 14 | 10400 | 11100 | 27 |
| 15 | 10500 | 11000 | 26 |
| 16 | | 10900 | 25 |
| 17 | 10600 | 10800 | 24 |
| 18 | 10700 | | 23 |
| 19 | | 10703 | 22 |
| 20 | 10701 | | 21 |

| | | | |
|----|--------|-------|----|
| 12 | | | |
| 13 | 9000 | 10000 | 28 |
| 14 | 9102 | 9900 | 27 |
| 15 | 9100 | 9800 | 26 |
| 16 | KRUSES | 9101 | 25 |
| 17 | 9200 | 9700 | 24 |
| 18 | 9300 | 9600 | 23 |
| 19 | 9302 | 9500 | 22 |
| 20 | 9301 | 9400 | 21 |

| | |
|---|--|
| 1 | |
| 2 | |
| 3 | |
| 4 | |

| | | | |
|---|--------|------|---|
| 1 | 7201 | 7202 | 8 |
| 2 | SECOND | | 7 |
| 3 | 7200 | 7300 | 6 |
| 4 | | | 5 |

| | | | | |
|------|------|------|------|------|
| 1 | 4 | 5 | 8 | 9 |
| 7400 | 7403 | 7402 | 7401 | 7600 |
| ADD | | | | |
| 2 | 3 | 6 | 7 | 10 |
| 7405 | 7404 | 7500 | | |

E

10-05

BLVD.

| | |
|---------|---|
| VACATED | |
| 6300 | 1 |
| 6400 | 2 |
| 6401 | 3 |
| 6401 | 4 |

| | | | |
|---|------|------|----|
| 1 | 5200 | 6200 | 34 |
| 2 | 5300 | | 33 |
| 3 | 5400 | 6100 | 32 |
| 4 | 5500 | 6000 | 31 |

| | | | |
|---|------|------|----|
| 1 | 4600 | 4700 | 38 |
| 2 | | | 37 |
| 3 | 4803 | 4701 | 36 |
| 4 | 4800 | DD | 35 |